





???????? (????????):



???????

Material index	A [mm]	B [mm]	C [mm]	D [mm]
6807400060110040AS	400	60	110	40
6807250045090035AS	250	45	90	35
6807350045090035AS	350	45	90	35
6807300045090035AS	300	45	90	35
6807200045090035AS	200	45	90	35
6807400045090035AS	400	45	35	35
6807150045090034AS	150	45	90	34